



Poz. 11, SKF SA 70 CS-2Z Serii nalu rulman bulunama-  
 diği için 15.01.02-10/11 i olarak yeni yaklakına düzeni  
 onjinele çizildi.  
 NOT  
 Poz. 11, SA 70 CS-2Z Serii nalu SKF imatli parça  
 bulunamadığı takdirde diğer parça imatli çekil.  
 Makazara Sinter Baza Makazara Gümmüşçük

15.01.02-10  
 Kumruoğlu  
 BMA  
 Mechanische Teile  
 5110044

115 H7	115 H7
125 H7	125 H7
140 H6	140 H6
150 H6	150 H6
160 H6	160 H6
170 H6	170 H6
180 H6	180 H6
190 H6	190 H6
200 H6	200 H6
215 H7	215 H7
230 H7	230 H7
250 H7	250 H7
270 H7	270 H7
280 H7	280 H7
300 H7	300 H7
315 H7	315 H7
330 H7	330 H7
350 H7	350 H7
370 H7	370 H7
390 H7	390 H7
400 H7	400 H7
420 H7	420 H7
450 H7	450 H7
470 H7	470 H7
500 H7	500 H7
520 H7	520 H7
550 H7	550 H7
570 H7	570 H7
600 H7	600 H7
630 H7	630 H7
650 H7	650 H7
670 H7	670 H7
700 H7	700 H7
720 H7	720 H7
750 H7	750 H7
770 H7	770 H7
800 H7	800 H7
820 H7	820 H7
850 H7	850 H7
870 H7	870 H7
900 H7	900 H7
920 H7	920 H7
950 H7	950 H7
970 H7	970 H7
1000 H7	1000 H7